From: Bob Goodhart
To: ENERGYSTARVerificationProgram@energystar.gov;
Subject: ENERGY STAR Product Requirements for Roof Products - Draft 2.2
Date: Friday, September 17, 2010 10:33:22 AM

Dear Sir or Madam:

I am reviewing the document in the subject line and gathering my comments. However, I found that the document is incomplete. The last section of the document is titled "Test Method: Maintenance of Solar Reflectance." It states that methods A, B, C, or D can be used. The document ends abruptly in Test Method C, with no mention of the last method. Please let me know when the corrected document is posted so I can respond to you with all of my comments at the same time.

Thank you,

Robert Goodhart
Product & Process Development
P: 610.395.8445 x 261
F: 610.395.9342

ATAS International, Inc.
ATAS
ENERGY EFFICIENT BUILDING ENVELOPE TECHNOLOGY
Metal Walls · Metal Roofs · Metal Ceilings · Metal Accessories
Allentown, PA
Mesa, AZ
Maryville, TN
www.atas.com
P: 610.395.8445 or 800.468.1441

Please consider the environment before printing this e-mail.

Disclaimer: This communication, together with any attachments hereto or links contained herein, is for the use of the intended recipient(s) and may contain information that is confidential or legally protected. If you are not the intended recipient, you are hereby notified that any review, disclosure, copying, dissemination, distribution or use of this communication is STRICTLY PROHIBITED. If you have received this communication in error, please notify the sender immediately by return e-mail message and delete the original and all copies of the communication, along with any attachments hereto or links herein, from your system. Thank you, for your cooperation.