

We would like to make the following comments:

1. ULF's should be separated completely in some manner so as to not confuse the details of testing the Lab grade freezers.
2. Relative to the last two sentences in 5 A) 4) a), provide a figure to clarify the thermocouple placements between and on adjacent shelves.
3. Please correct the tolerance in 6.5 A): $0.1 \text{ L} = 0.0035 \text{ ft}^3$; conversely $0.01 \text{ ft}^3 = 0.28 \text{ L}$

Glenn Bonney
Sr. Project Engineer



801 Church Lane
Easton, PA 18040-6673

gbonney@follettice.com

office: 800 523 9361 x307

610 252 7301 x307

mobile: 610 554 8143