

## **ENERGY STAR Windows, Doors, and Skylights Industry Stakeholders Meeting Agenda and Information**

December 12, 2014 1:00 – 4:00 PM

U.S. Environmental Protection Agency  
William Jefferson Clinton East  
1200 Pennsylvania Ave, NW  
Washington, DC 20460

**Purpose of the Meeting:** The purpose of the meeting is to review the ENERGY STAR specification revision process, discuss opportunities to make the process clearer and more predictable, and encourage more collaboration with industry. EPA will seek stakeholder feedback on a number of topics, including data sources, methodologies, and the decision making process. Stakeholders will be encouraged to provide input during the meeting as well as submit written feedback after the meeting. EPA has not decided to change the criteria, has not developed target criteria for the future, and will not be discussing any specific criteria proposals at this early stage.

### **Preliminary Agenda:**

- 1) Welcome and Introduction
    - a) Meeting Goals
    - b) Guide for Stakeholder Participation
    - c) Meeting Agenda
  
  - 2) ENERGY STAR Program Overview
    - a) Program Design
    - b) Windows, Doors, and Skylights Program History
    - c) Specification Revision Process
    - d) Transparency and Confidentiality
    - e) When to Review Specifications for Possible Revision
    - f) Guiding Principles for Specification Revision
  
  - 3) Review of Guiding Principles
    - a) National Energy Savings
    - b) Maintaining Product Performance
    - c) Cost-Effectiveness
    - d) Product Availability
    - e) Measurement and Verification
    - f) Market Differentiation
- Note:** For each Guiding Principle, EPA and stakeholders will discuss how the principle can be assessed for the Windows, Doors, and Skylights program, including potential methodologies, data sources and other important issues to consider.
- 4) Additional Discussion
  
  - 5) Next Steps
    - a) Framework Document
    - b) Timing
    - c) How to Provide Feedback

## Getting to EPA:

The meeting will be held in the William Jefferson Clinton Building East, at EPA's Federal Triangle campus.

The entrance to the building is located on Constitution Ave NW, near the corner of 12<sup>th</sup> Street NW. (See the red arrow on the map below).

For complete directions, please visit EPA's website:

<http://www2.epa.gov/aboutepa/visiting-epa-headquarters>

## Building Access:

Please note that guests visiting EPA:

- Need to have an acceptable form of photo identification, such as a driver's license, to enter;
- May be asked to go through a metal detector; and
- Must be signed in and escorted by an EPA employee

**Please note that driver's licenses from the following states and territory do not comply with REAL ID Act requirements and will not be considered acceptable forms of photo IDs: American Samoa, Arizona, Louisiana, Maine, Minnesota, New York, Oklahoma, and Washington.** Individuals from these states will need to present alternative forms of identification, described here: <http://www2.epa.gov/aboutepa/visiting-epa-headquarters> (Click on the Building Access tab)

To attend the meeting, all stakeholders must also register with EPA before December 5 by emailing [windows@energystar.gov](mailto:windows@energystar.gov). Program staff will reply to confirm that you have been added to the attendee list. If you are not on the list of registered attendees, you will not be able to enter the building. Receipt of this Stakeholders Meeting Agenda and Information document is not confirmation that you have successfully registered.

## Webinar:

The Stakeholders Meeting will be broadcast simultaneously via webinar. Webinar participants will also have an opportunity to comment and ask questions.

Information for accessing the webinar, such as a dial-in number and URL, is not yet available. EPA will send out additional information one week prior to the meeting.

## More Information:

Please contact [windows@energystar.gov](mailto:windows@energystar.gov) for more information.

